

## Product Specification for Smooth Sleeve


Document No : ZQK-331(OT1)

### 1. Applications and Features

Purpose	Simplified pipe penetrations for hot water heaters		
Location	ALC penetration of piping for hot water heater		
Features	<ul> <li>Multiple pipes and cables (water, gas, electricity, etc.) can be completed in a single core hole.</li> </ul>		
	The seal packing adheres tightly to various pipes and cables		
	to prevent water intrusion. Therefore, caulking is not required.		


# 2. Piping and cable location The following figure shows the location of piping and cables.

### Specification A



No.	Name	Applicable size
1	Floor heating (spare)	Sheath pipe 23.5×36(Oval)
2	Bathroom drying	Sheath pipe 23.5×36(Oval)
3	Floor heating	Sheath pipe 23.5×36(Oval)
4	Floor heating	Sheath pipe 23.5×36(Oval)
(5)	Reheating bathwater	Sheath pipe φ34
6	Gass	Sheath pipe φ32
7	Hot-water supply	Sheath pipe φ30.5
8	Water supply	Sheath pipe φ30.5
9	Power electrics	Cable VVF1.6
10	Weak electric current	Cable φ6.6
(11)	Weak electric current	Cable φ6.6
12	Weak electric current	Cable φ6.6

## Specification B



No.	Name	Applicable size
1	Floor heating (spare)	Sheath pipe φ27.5
2	Bathroom drying	Sheath pipe φ36.5
3	Floor heating	Sheath pipe φ27.5
4	Floor heating	Sheath pipe φ27.5
(5)	Reheating bathwater	Sheath pipe φ36.5
6	Gass	Sheath pipe φ36.5
7	Hot-water supply	Sheath pipe φ30.5
8	Water supply	Sheath pipe φ30.5
9	Power electrics	Cable VVF1.6
10	Weak electric current	Cable φ6.6
(1)	Weak electric current	Cable φ6.6
12	Weak electric current	Cable φ6.6

 $\times$ In addition to  $\phi$  160,  $\phi$  200 and  $\phi$  100 models are also available.



## Product Specification for Smooth Sleeve

Document No : ZQK-331(OT1)

### 3. Inspection

Inspection items: Visual inspection, Dimensional inspection

Frequency: Visual inspection are all products.

Dimensional inspections are sampling inspections.

#### 4. Notes

- Avoid direct sunlight. Be sure to install a water heater cover or similar covering to prevent exposure to sunlight.
- If gaps are found between the seal packing and the ALC board, caulk the gap separately.
- Piping and cables must be inserted in place.
   Inserting them in the wrong places may cause gaps.